FACTORY

Disassembly Instructions

People: 2 people Tools : cordless drill, screw driver set, hex drive set, wrench set Skill Set: good manual dexterity. Estimated Time: 16-19 minutes per Factory Table

1. Table Top: 6 mins

Flip over the Factory Table and remove the wood screws that attach the base to the tops.

2. Table Stretcher: 8 mins

Remove the bolts from the ends and bottom sides of the table stretcher (4 per end and 1 per bottom) 3a. Glide: 2mins Turn the glide counter clockwise to remove. (x4) 3b. Casters: 5mins Using a open ended wrench remove the casters (x4)

Recyclable Material (lbs)	
Wood	69.9 - 105.9
Steel	64.1 - 85
Laminate	8.8 - 13.7
Edge	1.6 - 2.1
Total Weight	144.4 - 206.7



