






# SNOWBALL


## Connected Seating




# 1




# 2



# 3





**Spec Furniture Inc.**  
165 City View Drive, Toronto ON, M9W 5B1  
**P:** 416.246.5540 | **F:** 416.246.5547  
**E:** [specit@specfurniture.com](mailto:specit@specfurniture.com) | [specfurniture.com](http://specfurniture.com)






# SNOWBALL



## Upholstery Replacement



### BACK REPLACEMENT




### SEAT REPLACEMENT




**Note: Do not over-tighten fasteners.**

## BACK REPLACEMENT



# 1





# 2



# 3




# 4






## SEAT REPLACEMENT



# 1




# 2



# 3



# 4




**Spec Furniture Inc.**

165 City View Drive, Toronto ON, M9W 5B1





**P:** 416.246.5540 | **F:** 416.246.5547

**E:** [specit@specfurniture.com](mailto:specit@specfurniture.com) | [specfurniture.com](http://specfurniture.com)





# SNOWBALL


## Arm Replacement



# 1




REMOVE OLD ARMS BY STRIKING WITH A MALLET.




**\*NOTE:** IF ARM IS BROKEN, PUSH THE BROKEN STUD APPROXIMATELY 2" INTO THE TUBE.

# 2



LOCATE ARM ENDS INTO THE TUBE ENDS.

# 3




**Spec Furniture Inc.**

165 City View Drive, Toronto ON, M9W 5B1

**P:** 416.246.5540 | **F:** 416.246.5547





**E:** [specit@specfurniture.com](mailto:specit@specfurniture.com) | [specfurniture.com](http://specfurniture.com)




# SNOWBALL

Connected Seating with Tables






# 1



# 2



# 3

