






# EIGHTEEN5 / TWENTY2


## Seat Replacement




# 1





# 2




# 3



# 4



5




**Spec Furniture Inc.**

165 City View Drive, Toronto ON, M9W 5B1





**P:** 416.246.5540 | **F:** 416.246.5547

**E:** [specit@specfurniture.com](mailto:specit@specfurniture.com) | [specfurniture.com](http://specfurniture.com)




# EIGHTEEN5 / TWENTY2

## Back Replacement







# 1




# 2




# 3



# 4



5



**Alternate impacts until back is fully on.**

**Spec Furniture Inc.**

165 City View Drive, Toronto ON, M9W 5B1

**P:** 416.246.5540 | **F:** 416.246.5547

**E:** [specit@specfurniture.com](mailto:specit@specfurniture.com) | [specfurniture.com](http://specfurniture.com)